

ASSEMBLY INSTRUCTION

Check teithen after few hours.

Link to download pdf version : www.3dplex.fr/files/assembly_inst_um_coverv1.1.pdf

<p>1</p> <h3>Necessary screws</h3> <ul style="list-style-type: none">For dia.3mm HEX screwsFor dia.4mm HEX screwsPlat screwdriverPhillips screwdriver	<p>2</p>	<p>3</p> <p>C X52 STD X54 EXT D X2 F X4 B 12mm X2 A 10mm x50 STD x52 EXT E X4 H X2 G X2 I X2 DIA.3mm DIA.4mm DIA.2mm DIA.3mm</p>
<p>4</p>	<p>5</p> <p>Firmly insert nuts</p>	<p>6</p> <p>A x 5 A x 4 H x 2</p>
<p>7</p> <p>F x 2</p>	<p>8</p> <p>POWER FAN CONNECTOR G x 2</p>	<p>9</p> <p>H x 2</p>
<p>10</p> <p>C x 15 A x 15</p>	<p>11</p> <p>C x 15 A x 15</p>	<p>12</p>
<p>13</p>	<p>14</p>	<p>15</p> <p>E x 4 F x 4</p>

